
SA040 Work Light Mounting Instruction
Scope of delivery:

- 1 Lamp
- Connecting line



A.Unscrew the nut and the gaskets




B.Attach lamp to a base. Add nut and washer and Spring washer to screw.



C.Loosen the fixing screws on both sides of the u-shaped bracket to adjust the angle of lamp, then fix it back



D.Connecting the lamp to battery.



Notes:

- Remove the protective film from the lens after installation.
- 2 Please ensure there is no covering in front of the lighting direct.
- 3 If the additional cable set is needed, the min current should be >5A.
- 4 Waterproof sealing is a must for cable connect.
- 5 The lamp can be mounted in two ways: front mounted or back mounted
- 6 When the lamp is heated to 70 ° after electrification, the panel will stop heating, and when the temperature drops to 0°, the lamp will restart the heating function